

Montageanleitung

- Diese Anleitung gilt nur in Verbindung mit der Montage-, Betriebs- und Wartungsanleitung des 'reflex DD'.
- Die 'flowjet' Durchströmungsarmatur ist nur in Verbindung mit 'reflex DD' einzusetzen.

'reflex DD' bis Anschlag gewindedichtend in 'flowjet' eindrehen (Armaturen mit innenliegendem O-Ring brauchen nicht mit zusätzlichem Dichtmittel eingedichtet werden).

Einstellschraube:
Bitte Drehrichtung beachten (→ Beschriftung auf der Armatur).

'flowjet' gewindedichtend in T-Stück eindrehen bis ca. 2 Gewindegänge vor Anschlag.

- Aufgedruckte Strömungsrichtung beachten.
- Bei Verwendung anderer T-Stücke bitte beachten:
= Rp $\frac{3}{4}$ Lanze muss **frei** in Strömung ragen

Mounting instructions

- Instructions to be followed for installation, maintenance and operating of 'reflex DD' expansion vessel.
- 'flowjet' flow fitting is to be used only in combination with 'reflex DD' vessel.

Turn in 'flowjet' into thread of 'reflex DD' until stop screw (Fittings with O-ring on the inside do not need to be sealed in with additional sealant).

Setting screw:
Please note rotating direction (→ label on the installation).

Turn in 'flowjet' into T-piece until approx. 2 thread turns before stop screw.

- Follow direction of flow as indicated.
- For use with another T-piece, please consider:
= Rp $\frac{3}{4}$ Lance must be **free** to protrude in flow

